

# Culebra Landfill, Puerto Rico

## Inspection Photo Album



29 NOVEMBER 2018

U.S. EPA

by Region 2 DECA-RCB (Carl Plössl)







EPA Region 2 RCRA inspectors Plössl and McCleary, along with the ORD team, were met at the airport by Juan Mercado, the Landfill Engineer of record and a municipal driver and van. We were transported to and arrived at the Culebra Landfill at 1:00 pm on November 29 for the inspection and evaluation.





PROHIBIDO  
BOTAR  
BASURA  
\$500 MULTA

















